WS1 Pro - Probes Accessories

Description External Probes & UbiBot Cloud IoT Platform Specifications Downloads and Documents FAQs

UbiBot WS1 Pro has two Micro USB ports for connecting external probes or USB power supply.


- Each Micro USB port supports 1 x DS18B20 temperature probe.
- The lower Micro USB port also supports the following RS485 probes:


TH30S-B Air Temperature and Humidity Probe Soil Temperature and Moisture Sensor PT 100 Industrial-grade Temperature Probe Wind Speed Sensor


- Splitters may be needed when you connect multiple external probes and external USB power supply at the same time.

NOTE

- For RS485 probe, only one of each type can be connected at a time.







External	Probes

DS18B20 Temperature Probe	More details
TH30S-B Air Temperature and Humidity Probe	More details
Soil Temperature and Moisture Sensor	More details
PT 100 Industrial-grade Temperature Probe	More details
Wind Speed Sensor	More details

Accessories

	WS1	WS1 Pro	GS1	GS2
Internal sensors				
Temperature Temperature	•	•	•	
Humidity	•	•	•	
- Ambient light	•	•	0	•
External snesors				
DS18B20	•	•	0	•
Wind speed sensor		•	0	
Ambient light sensor			0	
PT100		•	0	
Soil temperature and moisture sensor		•	0	
TH30S-B		•	0	
CO2 sensor			0	
EC EC	_			•
cim PH				(•)
Other accessories				
Water resistant cover	•	•		
Probe adapter	•	•	0	
Solar panel			•	•
Strobe light and siren alarm			0	0
PoE splitter			0	